

CASE HISTORY :- CASTLE GARAGE, WHITWICK, LEICESTERSHIRE

ARCHITECT	HOWARD WARD ASSOCIATES
CONTRACTOR	McCANE CONSTRUCTION
CONSTRUCTION	2002
GABION WALL DESIGN	HY-TEN GABION SOLUTIONS



A new gabion wall was constructed after the original structure was washed away by flood Water from the adjacent road. The flood also undermined an extension to the adjacent building which was rebuilt on piled footings.

CASE HISTORY :- HARBOURNE, GOLF CLUB, BIRMINGHAM

ENGINEER	UNKNOWN
CONTRACTOR	PC CONSTRUCTION
CONSTRUCTION	2003
GABION SUPPLY	HY-TEN GABION SOLUTIONS



Reinstatement to an existing water course on the golf course was carried out with 300mm deep gabion mattress channel lining. The gabions supplied were Green PVC-Zinc mesh 76.2mm x76.2mm x 2.7mm filled on site with rock fill to the bed of the water course and for the banks a soil/rockfill mix was used with the top face lined with a bio-degradeable matting to help promote the establishment of natural vegetation.

This photograph was taken a few months after completion and the vegetation is starting to become establish.